


**Final
Draft**



References:

Baseline Ecological Risk Assessment, Shpack Landfill Superfund Site, Metcalf & Eddy, Inc., 2004

Focused Site Inspection: Characterization Surveys for Radiological Contaminants of Concern, Shpack Landfill Superfund Site, Cabrera Services, Inc., 2003

**Draft
Final**





Figure 6 - RCRA-C Landfill Cap Schematic Cross-Section
Shpack Landfill Superfund Site - Norton and Attleboro, MA



**Draft
Final**




Figure 7 - Potential Cap Schematic Layout - Plan View
Shpack Superfund Site - Norton and Attleboro, MA

